

Deteriorating Buildings: Ticking Time Bombs

TH205

Thursday, June 21, 2018 | 7:30 AM – 9:00 AM

1.5 Learning Units

This presentation is protected by U.S. and international copyright laws.

Reproduction, distribution, display and use of the presentation without written permission of the speaker is prohibited.

This program is registered with the AIA/CES for continuing professional education. As such, it does not include content that may be deemed or construed to constitute approval, sponsorship or endorsement by AIA of any method, product, service, enterprise or organization.

The statements expressed by speakers, panelists, and other participants reflect their own views and do not necessarily reflect the views or positions of The American Institute of Architects, or of AIA components, or those of their respective officers, directors, members, employees, or other organizations, groups or individuals associated with them.

Questions related to specific products and services may be addressed at the conclusion of this presentation.

Acknowledgements/Credits

929Media

Adobe Stock

Chicago Architecture Foundation

Shutterstock

Alexei Tajzler, RA

Andrew Halpin

Anthony Malara, RA, LEED AP

Andrew E. Zimmerman, RA

Ashley Griffith

Daniel Burlew

Flora Kwitman

Jane Felsen Gertler, FSMPS

Joseph Nevins

Margaret Hovorka

Moondeep Pradhananga, RA

Phil Wong

Stephanie Bush, RA, LEED AP

Speakers List

- **Howard L. Zimmerman, FAIA [Moderator]**
Principal, Howard L. Zimmerman Architects, PC
- **Joan Berkowitz, FAPT**
Senior Project Manager/Senior Preservationist
Howard L. Zimmerman Architects, PC
- **Charles Bransby-Zachary, BSc MRICS**
Principal, CBZ Consulting
- **David B. Peraza, PE**
Principal Engineer, Exponent Engineering, PC

Course / Learning Objectives

- Learn how to identify aging conditions and their potential resulting problems, as well as the necessity for regulating statutes.
- Begin to comprehend applicable methods of investigation and assessment through a variety of investigation methodologies (e.g., visual, low-tech, high-tech, nondestructive and destructive).
- Learn to identify possible causes of deterioration, such as ferrous metals, water infiltration, poor initial design, poorly executed repairs, structural issues, and material properties, and to determine whether a problem is isolated or systemic.
- Explore the repair methodologies best-suited to the problem, material, municipal requirements, and project schedule and budget.

Agenda

SAFETY IN THE URBAN ENVIRONMENT
LOAD BEARING MASONRY
MATERIALS THROUGHOUT HISTORY
CONCEALED METAL
TERRA COTTA
STEEL FRAME

CAVITY WALL
CONTEMPORARY CONSTRUCTION
MATERIAL DEFECTS
SUPERTALLS
HUMAN ERROR
SUMMARY

Agenda

SAFETY IN THE URBAN ENVIRONMENT

LOAD BEARING MASONRY

MATERIALS THROUGHOUT HISTORY

CONCEALED METAL

TERRA COTTA

STEEL FRAME

CAVITY WALL

CONTEMPORARY CONSTRUCTION

MATERIAL DEFECTS

SUPERTALLS

HUMAN ERROR

SUMMARY

LOAD BEARING MASONRY



Medieval Castle Kent, South East England (1127)

Observed Conditions Falling Masonry

Investigation Methods GPR; Infrared Thermal Imaging

Root Causes No Rain Water Discharge; Exterior Wall Tops Exposed

Potential Repair Grout & Repointing; New Roof; Water Discharge System

885 years to failure



LOAD BEARING MASONRY

**erosion at 15-foot
solid stone wall
(image looking up)**





1



2

LOAD BEARING MASONRY



thermal imaging showing moisture retention at parapet



Agenda

SAFETY IN THE URBAN ENVIRONMENT

LOAD BEARING MASONRY

MATERIALS THROUGHOUT HISTORY

CONCEALED METAL

TERRA COTTA

STEEL FRAME

CAVITY WALL

CONTEMPORARY CONSTRUCTION

MATERIAL DEFECTS

SUPERTALLS

HUMAN ERROR

SUMMARY


MATERIALS THROUGHOUT HISTORY

Load Bearing Masonry

1



2



Examples of Flying Buttresses Basilica of San Vitale, Ravenna, Italy (547); Notre Dame Cathedral, Paris, France (1345)

MATERIALS THROUGHOUT HISTORY

1


Cast & Wrought Iron



2



3



Examples of Cast & Wrought Iron Construction The Iron Bridge, Shropshire, England (1781); Tay Bridge Disaster, Dundee, Scotland (1887); Eiffel Tower, Paris, France (1889)

MATERIALS THROUGHOUT HISTORY


Load Bearing Masonry



Modern Load Bearing Construction Monadnock Building, Chicago, Illinois, USA (1891)

MATERIALS THROUGHOUT HISTORY

Load Bearing Masonry



QUERSCHNITT.



NORDANSICHT


MONADNOCK BLOCK CHICAGO 1891

ARCHITEKTEN BURNHAM & ROOT

Modern Load Bearing Construction Monadnock Building, Chicago, Illinois, USA (1891)

MATERIALS THROUGHOUT HISTORY

Masonry & Steel



Masonry & Steel Construction 666 Greenwich Village, New York, New York, USA (1899)

Agenda

SAFETY IN THE URBAN ENVIRONMENT

LOAD BEARING MASONRY

MATERIALS THROUGHOUT HISTORY

CONCEALED METAL

TERRA COTTA

STEEL FRAME

CAVITY WALL

CONTEMPORARY CONSTRUCTION

MATERIAL DEFECTS

SUPERTALLS

HUMAN ERROR

SUMMARY

CONCEALED METAL

Upper West Side Beaux-Arts Building New York, New York, USA (1906)


Observed Conditions Horizontal Cracks at Cornices & Water Tables

Investigation Methods Visual

Root Causes Steel Corrosion

Potential Repair Parapet Replacement

101 years to failure



CONCEALED METAL

2



1

damage invisible to the naked eye



3



CONCEALED METAL

shifting terra
cotta units



1



horizontal cracking
at cornice



2

CONCEALED METAL



1




2



severely corroded steel anchors

3

CONCEALED METAL



Early 20th Century Beaux-Arts Building Washington, District of Columbia, USA (1908)

Observed Conditions Modillion Failure

Investigation Methods Visual; Ultrasonic

Root Causes Anchor Corrosion; Marble Deterioration

Potential Repair Angled Stainless Steel Rod Anchorage; Pinning

106 years to failure

CONCEALED METAL



1



2



3



4

CONCEALED METAL



Agenda

SAFETY IN THE URBAN ENVIRONMENT

LOAD BEARING MASONRY

MATERIALS THROUGHOUT HISTORY

CONCEALED METAL

TERRA COTTA

STEEL FRAME

CAVITY WALL

CONTEMPORARY CONSTRUCTION

MATERIAL DEFECTS

SUPERTALLS

HUMAN ERROR

SUMMARY



Esplanade Venture charged in facade collapse that killed child

Two-year-old died in 2015 accident at 305 West End Avenue

Engineer Accused of Failing to Assess Manhattan Building Where Falling Debris Killed Girl

By Rick Rojas Nov. 17, 2015



Maqsood Faruqi, 55, has been charged with offering a false instrument for filing with the New York City Department of Investigation.

Six months after a terra cotta windowsill crumbled and fell some 600 feet, fatally striking 2-year-old girl on the Upper West Side of Manhattan, investigators announced on Tuesday that they had found a trail of negligence leading to the engineer who was hired to inspect the building.

Girl, 2, Dies After Being Hit by Falling Facade in Manhattan

By Al Baker May 17, 2015

A 2-year-old girl died Monday from injuries she sustained when a brick facade broke free from a building on Manhattan's Upper West Side and rained down on her and her grandmother as they sat on a bench below, the authorities said.


The girl, Greta Greene of Brooklyn, was struck in the head when bricks from a portion of an eighth-floor window ledge gave way.


Her grandmother, Susan Frierson, 60, was struck in the wrist and had minor injuries, the police said.

The episode occurred around 11:05 a.m. outside the Esplanade home for older adults on West End Avenue between West 107th and 108th Streets, officials said.

Responding emergency workers took Greta to [NewYork-Presbyterian Hospital/Weill Cornell Medical Center](#), where the police said she underwent surgery.

A spokesman for the city's Buildings Department said an order of violation had been issued to the building's owner, Esplanade.





TERRA COTTA

Midtown Beaux-Arts Building New York, New York, USA (1929)

Observed Conditions Terra Cotta Spalling

Investigation Methods GPR; Impact Echo; Ultrasonics; Metal Detection

Root Causes Poor Support; Lack of Soft Joint

Potential Repair Pinning of Bracket Scrolls

80 years to failure

TERRA COTTA

2



1




3



4



TERRA COTTA



Agenda

SAFETY IN THE URBAN ENVIRONMENT

LOAD BEARING MASONRY

MATERIALS THROUGHOUT HISTORY

CONCEALED METAL

TERRA COTTA

STEEL FRAME

CAVITY WALL

CONTEMPORARY CONSTRUCTION

MATERIAL DEFECTS

SUPERTALLS

HUMAN ERROR

SUMMARY

STEEL FRAME

Stone Panels

1



Financial District Art Deco Building New York, New York, USA (1929)

Observed Conditions Vertical Cracking of Limestone

Investigation Methods Visual; Probes; GPR; Metal Detection

Root Causes Steel Sizing Design; Steel Corrosion

Potential Repair Replace Stone; Modify Steel; New Expansion Joints

87 years to failure

2



STEEL FRAME

Stone Panels

**vertical cracks
in stone visible
across surface**

1



2



3



STEEL FRAME

Stone Panels




STEEL FRAME

Stone Panels

**vertical cracks in
stone not visible on
the surface**

1

2



STEEL FRAME

Stone Panels

1

2

3

Midtown Art Deco Building New York, New York, USA (1931)



Observed Conditions Vertical Cracking of Limestone

Investigation Methods Visual; Probes; GPR; Metal Detection

Root Causes Steel Corrosion

Potential Repair Steel & Limestone Replacement

68 years to failure



STEEL FRAME

Stone Panels

Midtown Art Deco Building New York, New York, USA (1929)

Observed Conditions Steel Deterioration; Cracking; Spalling

Investigation Methods Sounding; Ultrasonic Thickness Gauge; Probes

Root Causes Corroding Steel Behind Terra Cotta

Potential Repair Steel Cleaning and Waterproofing; Terra Cotta Replace

88 years to failure



STEEL FRAME

Stone Panels



1



2




3

STEEL FRAME

Stone Panels



1



**corroded steel section
with no waterproofing
wrapped in masonry**

2



3

STEEL FRAME

Bonded Wall

1



Upper West Side Art Deco Building New York, New York, USA (1931)

Observed Conditions Cracked Masonry


Investigation Methods Visual; Probes

Root Causes Material Corrosion

Potential Repair Steel Replacement

68 years to failure

2



STEEL FRAME

Bonded Wall

2

ORIGINAL STEEL SECTION

RUST EXPANSION



1



3

COLUMN



STEEL FRAME

Bonded Wall



Examples of Common Bonded Wall Hidden Conditions Various Locations

STEEL FRAME

Stone Panels

1

Lenox Hill Art Deco Building New York, New York, USA (1929)

Observed Conditions None Visible (Spalling of Rear Stone Face)

Investigation Methods GPR; Metal Detection; Infrared Thermal Imaging

Root Causes Material Corrosion

Potential Repair Stone and Anchor Replacement


79 years to failure

2



STEEL FRAME

Stone Panels




2

hidden cracking & spalling due to anchor corrosion



1




3

typically visible surface cracks & spalling



4



5

Agenda

SAFETY IN THE URBAN ENVIRONMENT
LOAD BEARING MASONRY
MATERIALS THROUGHOUT HISTORY
CONCEALED METAL
TERRA COTTA
STEEL FRAME

CAVITY WALL
CONTEMPORARY CONSTRUCTION
MATERIAL DEFECTS
SUPERTALLS
HUMAN ERROR
SUMMARY

CAVITY WALL

1



2



3



Midtown International Style Building New York, New York, USA (1957)

Observed Conditions Brick Panel Failure/Partial Collapse

Investigation Methods Visual; Thermography; GPR; Metal Detection

Root Causes Field Modifications; No Soft Joints/Relieving Angles

Potential Repair Spandrel Panel Replacement; Reskin

40 years to failure

CAVITY WALL

1



Lenox Hill Late Modernist Building New York, New York, USA (1965)

Observed Conditions Brick Panel Failure/Partial Collapse

Investigation Methods Visual; Thermography; GPR; Metal Detection

Root Causes Material Corrosion


Potential Repair Post-Installed Anchors; Reskin

50 years to failure

2



3



CAVITY WALL

2



3



collapsed bricks held by waterproofing membrane

4



corroded brick ties

5



1





Owner to Dismantle Flawed Madison Ave. Facade

By CHARLES V. BAGLI

The developer Harry Macklowe said yesterday that he would dismantle the entire south facade of his 39-story tower at 540 Madison Avenue, brick by brick, rather than risk having another section of the wall break away from the building and tumble

bracing.

Officials said the avenue would remain closed to automobiles, at least until Monday night.

City officials say the building is now structurally stable, but the developer has decided not to try to salvage the remaining

serious problems with the brickwork around the end of October, the Macklowe Organization said. Fearing that bricks might come loose, workers began putting up safety nets several weeks later, and the contractor obtained a permit on Nov. 25 for a sidewalk shed along Madison Avenue.

High-Rise Wall Breaks Loose, Raining Debris On Shoppers

By DAVID M. HALBFINGER

A section of a Madison Avenue office tower's side wall suddenly peeled off yesterday, raining debris on holiday shoppers and tourists, snapping a hanging work platform in two and dangling a ton of bricks from a torn safety net.

A man and a 3-year-old girl were only slightly injured, but neighboring buildings were evacuated and several blocks were closed to traffic into the night. Hundreds of passers-by



A safety net was bent by the weight of bricks that tore loose from the Madison Avenue yesterday. Some of the debris fell on the streets.



Midtown Late Modernist Building New York, New York, USA (1971)

Observed Conditions Bulging Masonry; Panel Failure/Partial Collapse

Investigation Methods Visual Thermography; Radar; Metal Detection

Root Causes Installation Error

Potential Repair Post Installed Anchors; Reskin

26 years to failure

tell while looking up at the falling bricks. He refused medical attention.

About half an hour after the initial shower of bricks, the platform snapped in two, and another wave of debris rained down on the street.

According to city officials and owners of the buildings next to the tower, about five months ago construction workers started punching holes in the brick wall and installing windows on every floor.

lowe Organization, did not respond to phone messages left at its office.


Ted Birkhahn, a spokesman for the Department of Buildings, said that in November, an architect or engineer working for the owner inspected the tower's facade and found that exterior brickwork was "pulling away" from a middle layer of brick in the cavity between exterior and interior masonry.

After hanging safety nets and work platforms, contractors also

CAVITY WALL



**bulging brick
prior to collapse**



**no dovetail
anchors in slot**



**brick veneer
balanced on
shelf angles**



CAVITY WALL

misaligned slots & steel elements



Upper West Side Late Modernist Building New York, New York, USA (1970)

Observed Conditions Cracked Masonry


Investigation Methods Visual; Probes

Root Causes Installation Error; Field Modifications; Poor Workmanship

Potential Repair Reskin; Relieving Angle Replacement; Pinning

47 years to failure

CAVITY WALL



Agenda

SAFETY IN THE URBAN ENVIRONMENT
LOAD BEARING MASONRY
MATERIALS THROUGHOUT HISTORY
CONCEALED METAL
TERRA COTTA
STEEL FRAME

CAVITY WALL
CONTEMPORARY CONSTRUCTION
MATERIAL DEFECTS
SUPERTALLS
HUMAN ERROR
SUMMARY

CONTEMPORARY CONSTRUCTION

Poured Reinforced Concrete

1



Upper East Side Contemporary Building New York, New York, USA (2005)


Observed Conditions Concrete Spalling

Investigation Methods Visual; Sounding; GPR; Metal Detection


Root Causes Concrete Coverage

Potential Repair Concrete Patching

10 years to failure



2



CONTEMPORARY CONSTRUCTION

Poured Reinforced Concrete

2

cracking due to improper placement of re-bar in concrete eyebrows

3


4

1

6

loose bricks due to rigid mortar mix

5







CONTEMPORARY CONSTRUCTION

Glass & Metal Envelopes


1

2

3



5



4

Financial District Contemporary Building New York, New York, USA (2008)


Observed Conditions Falling Curtain Wall Cladding

Investigation Methods Visual; Probes

Root Causes Workmanship

Potential Repair Façade Repairs

3 years to failure



Agenda

SAFETY IN THE URBAN ENVIRONMENT
LOAD BEARING MASONRY
MATERIALS THROUGHOUT HISTORY
CONCEALED METAL
TERRA COTTA
STEEL FRAME

CAVITY WALL
CONTEMPORARY CONSTRUCTION
MATERIAL DEFECTS
SUPERTALLS
HUMAN ERROR
SUMMARY

MATERIAL DEFECTS

Glass

1

2

Hell's Kitchen Contemporary Building New York, New York, USA (2007)



Observed Conditions Spontaneous Broken Glass

Investigation Methods Visual

Root Causes Nickel Sulfide (Manufacturing Defect)

Potential Repair Glass Replacement


1 year to failure



MATERIAL DEFECTS

Glass

2



3




4



1



6




5



MATERIAL DEFECTS

Brick

1



Early 20th Century Public Bathhouse Queens, New York, USA (1937)

2




5



3



4



MATERIAL DEFECTS

Gypsum


1




2




3



4



5



Academic Building New Haven, Connecticut, USA (1965)

MATERIAL DEFECTS

Gypsum



1



2



3



4

Romanesque Revival Basilica Brooklyn, New York, USA (1905)

MATERIAL DEFECTS

White Glazed Brick



1



2



3



5



4

Early 20th Century Commercial Building Queens, New York, USA (1930)

Agenda

SAFETY IN THE URBAN ENVIRONMENT
LOAD BEARING MASONRY
MATERIALS THROUGHOUT HISTORY
CONCEALED METAL
TERRA COTTA
STEEL FRAME

CAVITY WALL
CONTEMPORARY CONSTRUCTION
MATERIAL DEFECTS
SUPERTALLS
HUMAN ERROR
SUMMARY

SUPERTALLS

Tall and Narrow Structures -- What to expect?



Burj Khalifa (2,717ft)

United Arab Emirates (2008)



432 Park Avenue (1,396ft)

New York, USA (2015)



111 West 57th Street (1,428ft)

New York, USA (2019)



MoMA Tower (1,050ft)

New York, USA (2018)

SUPERTALLS

Tall and Narrow Structures -- What to expect?



9 DeKalb Avenue (1,030ft)

New York, USA (2021)



125 Greenwich Street (912ft)

New York, USA (2019)



30 Park Place (869ft)

New York, USA (2016)



111 West 57th Street (661ft)

New York, USA (2019)

Agenda

SAFETY IN THE URBAN ENVIRONMENT
LOAD BEARING MASONRY
MATERIALS THROUGHOUT HISTORY
CONCEALED METAL
TERRA COTTA
STEEL FRAME

CAVITY WALL
CONTEMPORARY CONSTRUCTION
MATERIAL DEFECTS
SUPERTALLS
HUMAN ERROR
SUMMARY

HUMAN ERROR

i.e. "Whoops!"



bulging due to improper formwork



expansion caused by steel corrosion



paper joints?

Examples of Hidden Conditions Caused by Human Error Various Locations

Agenda

SAFETY IN THE URBAN ENVIRONMENT
LOAD BEARING MASONRY
MATERIALS THROUGHOUT HISTORY
CONCEALED METAL
TERRA COTTA
STEEL FRAME

CAVITY WALL
CONTEMPORARY CONSTRUCTION
MATERIAL DEFECTS
SUPERTALLS
HUMAN ERROR
SUMMARY

What have we learned?
Where do we go moving forward?

Contact Information

- **Howard Zimmerman, FAIA**
Principal
- **Joan Berkowitz, FAPT**
Senior Project Manager/Senior Preservationist

Howard L. Zimmerman Architects, P.C.
11 West 30th Street
New York NY 10001
AIA2018@hlzimmerman.com
212.564.9393
www.hlzimmerman.com

- **Charles Bransby-Zachary, BSc MRICS**
Principal

CBZ Consulting
cbz@cbzconsulting.com
310.990.8062

- **David B. Peraza, PE**
Principal Engineer
dperaza@exponent.com

Exponent Engineering PC
420 Lexington Avenue, Suite 1740
New York, NY 10170
212.895.8100
www.exponent.com

Thank you!